


THREAD GAGES




4812-E

- To check and set screw cutting tools
- Made of medium carbon steel

| Code | Range | Thread type | Pitch |
|----------------|---------|-------------|--|
| 4812-12 | 2-12mm | Tr 30° | 2, 3, 4, 5, 6, 7, 8, 9, 10, 12mm |
| 4812-E | 1-10TPI | ACME 29° | 1, 1-1/3, 1-1/2, 1-3/4, 2, 2-1/2, 3, 4, 5, 6, 7, 8, 9, 10TPI |



4812-12



4812-E

Unit: mm

| | | |
|---|---|--|
| <p>check the angle of screw cutting tools</p> | <p>check the width of screw cutting tools</p> | <p>set the position of screw cutting tools</p> |
|---|---|--|